



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
HIDEAKI MITSUTAKE ET AL.	: Examiner: Ali Alavi)
Appln. No.: 09/512,359	: Group Art Unit: 2875)
Filed: February 24, 2000	·)
For: ELECTRON BEAM APPARATUS	Certificate
U.S. Patent No.: 6,803,715 β i) FEB 1 3 2006
Issued: October 12, 2004) February 3, 2006 of Correction

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION <u>UNDER RULES 322 AND 323</u>

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

02/08/2006 HALI11 00000114 6803715

01 FC:1811 100.00 OP

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Frank A. DeLucia Attorney for Patentees Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,803,715 BI

DATED

October 12, 2004

INVENTOR(S) :

HIDEAKI MITSUTAKE ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2

Line 11, "a" (second occurrence) should be deleted.

COLUMN 4

Line 22, "can not" should read --cannot--; and

Line 41, "can not" (both occurrences) should read --cannot--.

COLUMN 6

Line 10, "substrate;" should read --substrate,--.

COLUMN 11

Line 19, "is" should read -- are--; and

Line 61, "can not" should read --cannot--.

COLUMN 13

Line 66, "above described" should read -- above-described --.

COLUMN 16

Line 36, "While the" should read -- The--.

COLUMN 17

Line 6, "above described" should read --above-described--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

517960v1

PATENT NO. <u>US 6,803,715</u>

No. of add'l. copies @ 30¢ per page

 \Rightarrow

Staple Here Only! S.X.BLNIXL S.X.BLNIXL

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,803,715 BI

DATED

October 12, 2004

INVENTOR(S)

HIDEAKI MITSUTAKE ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 21

Line 19, "charged" should read --be charged--; and Line 35, "is" should be deleted.

COLUMN 22

Line 58, "above described" should read --above-described--.

COLUMN 24

Line 10, "above described" should read --above-described--; Line 28, "As" should read --A° --; and

Line 32, "As" should read --A°--.

COLUMN 26

Line 30, "can not" should read --cannot--; and

Line 55, "above described" should read --above-described--.

COLUMN 27

Line 64, "I'_{dM})," should read --I'_{dN}--; and

Line 66, " I'_{dM} More" should read -- I'_{dN} . More--;.

COLUMN 28

Line 41, "above described" should read --above-described--.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,803,715</u>

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

517960v1

No. of add'l. copies

@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,803,715 61

DATED

October 12, 2004

INVENTOR(S)

HIDEAKI MITSUTAKE ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 29

Line 11, " G_M " should read -- G_N --; and Line 58, "above described" should read --above-described--.

COLUMN 30

Line 12, "above described" should read --above-described--.

COLUMN 31

Line 32, "(10.6 [Torr])," should read --(10⁻⁶ [Torr])--.

COLUMN 33

Line 20, "that" should read --That--; and Line 56, "deposited:" should read --deposited--.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,803,715</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)



Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,803,715 BI

DATED

October 12, 2004

INVENTOR(S) :

HIDEAKI MITSUTAKE ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 38

Line 59, "claim 3," should read --claim 33,--; and Line 62, "prising" should read --prising:--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

517960v1

PATENT NO. <u>US 6,803,715</u>

No. of add'l. copies @ 30¢ per page



Staple UNITED TO THE PROPERTY OF THE PROPERTY

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

: 6,803,715 B

PATENT NO.

October 12

DATED

October 12, 2004

INVENTOR(S) :

HIDEAKI MITSUTAKE ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2

Line 11, "a" (second occurrence) should be deleted.

COLUMN 4

Line 22, "can not" should read --cannot--; and

Line 41, "can not" (both occurrences) should read --cannot--.

COLUMN 6

Line 10, "substrate;" should read --substrate,--.

COLUMN 11

Line 19, "is" should read -- are--; and

Line 61, "can not" should read --cannot--.

COLUMN 13

Line 66, "above described" should read --above-described--.

COLUMN 16

Line 36, "While the" should read -- The--.

COLUMN 17

Line 6, "above described" should read --above-described--.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,803,715</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

517960v1

No. of add'l. copies @ 30¢ per page



Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,803,715

DATED

October 12, 2004

INVENTOR(S) :

HIDEAKI MITSUTAKE ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 21

Line 19, "charged" should read --be charged--; and Line 35, "is" should be deleted.

COLUMN 22

Line 58, "above described" should read --above-described--.

COLUMN 24

Line 10, "above described" should read --above-described--; Line 28, "As" should read --A° --; and

Line 32, "As" should read --A°--.

COLUMN 26

Line 30, "can not" should read --cannot--; and

Line 55, "above described" should read --above-described--.

COLUMN 27

Line 64, "I'dM)," should read --I'dN--; and

Line 66, "I'dM More" should read --I'dN. More--;.

COLUMN 28

Line 41, "above described" should read --above-described--.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,803,715</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,803,715

DATED

October 12, 2004

INVENTOR(S) :

HIDEAKI MITSUTAKE ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 29

Line 11, " G_M " should read -- G_N --; and Line 58, "above described" should read --above-described--.

COLUMN 30

Line 12, "above described" should read --above-described--.

COLUMN 31

Line 32, "(10.6 [Torr])," should read --(10⁻⁶ [Torr])--.

COLUMN 33

Line 20, "that" should read --That--; and Line 56, "deposited:" should read --deposited--.


MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

PATENT NO. <u>US 6,803,715</u>

Form PTO 1050 (Rev. 3-82)



Staple Here Onlyl

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,803,715

DATED

October 12, 2004

INVENTOR(S) :

HIDEAKI MITSUTAKE ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 38

Line 59, "claim 3," should read --claim 33,--; and Line 62, "prising" should read --prising:--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

PATENT NO. <u>US 6,803,715</u>

Form PTO 1050 (Rev. 3-82)

